

Renewal $\frac{30}{31} \frac{29}{32}$ T32S R7W

Found 0 BT's

24" D. Fir now 25" N20E 31' $\frac{2}{3}$
Back scribe visible T32S R7W BT

30" D. Fir now 32" S65E 16' $\frac{5}{8}$
Back scribe visible T32S R7W

30" D. Fir now stub S55W 20' $\frac{5}{8}$

No Trace of NW BT.

Renewal

Set Brass cap at sec cor MAD,
county Surveyors office.

T32S R7W

$\frac{530}{531} \frac{529}{532}$

1968

New Bearing Trees

14" D. Fir N17 W 19' $\frac{2}{3}$
Scribed T32S R7W S30 c.s. BT

10" Pine S82 W 28' $\frac{1}{2}$
Scribed T32S R7W S31 c.s. BT

Relazed & Rescribed

25" D. Fir N20E 31' $\frac{2}{3}$
scribed T32S R7W S29 c.s. BT

32" D. Fir S65E 16' $\frac{5}{8}$
scribed T32S R7W S32 c.s. BT

Note:

This cor lies approx 40' West
of large Back outcrop. Also on
top of small spur running West.

3-21-67

O.K. J.W.B.

S. File No. 5426-117