

Renewal

26/25
25/36

T 325 R 7 W

Found:

O.B.T's

15" S. Pipe now 20" N 45 E 33°
No marks visible

20" D. Fir now 38" N 15 W (Rec. 180 W) 11 E
Bark scribe visible T 325 R 7 W 526 BT

16" D. Fir now down 56 W 40 Z (Rec. 36 Z)
Bark scribe visible T 32 and other marks

18" D. Fir now down SSE 40° (Rec. 35 Z)
Marks visible
Also unrecorded in Pipe at cor.

By using 3 Bearings and 2 Dist. I
Renew.

Set Brass cap at sec cor MKR
County Surveyors office

T 325 R 7 W

526/525
535/536

1960

New Bearing Trees:

14" D. Fir S 79 E 53°
Scribed T 325 R 7 W 536 CS BT

16" Laurel S 32 W 77 E
Scribed T 325 R 7 W 535 CS BT

Replaced & Rescribed

20" S. Pipe N 45 E 33°
Scribed T 325 R 7 W 525 CS BT

G. K. J. W. R.
77

C. S. File No. 57/86-123

DIETZEN NO. 385-6