

Revised

10/1
5/4

T325 R7W

Found

02373

16" Pipe Now 36" N77E 1007
opened for scribe "S11" "W"

10" Pipe Now Sharp Hole? S75E 1507
I find this mark at approx S75E 1507 NO EVIDENCE

10" Laurel Now Better Hole S38W 507

8" 4 Out Now Broken Stump N65W 627

Revised

Set Brass cap at Sec. car NKD,
county surveyors office

T323 R7W

S10 S11
S15 S14

1967

New Bearing Trees:

11" Laurel N66E 297
Scribed T325 R7W S11 E5 AT

9" Laurel S50 1/2 W 327
Scribed T325 R7W S15 E5 AT

7" D. Fir S57 1/2 E 287
Scribed T325 R7W S14 E5 AT

8" Laurel N44W 197
scribed T325 R7W S10 E5 AT

11-20-67
~~JWB~~
~~JWB~~
JWB

556 O.K. J.W.B.

C.S. File No. 54/36-142

DIETZGEN NO. 385-6