

Renewal

3/12  
10/11

T33S R7W

Found  
OBT

7" Maple NW 1/4 NW 1/4 N 3/4 E 60' (Recon 32E)

36" D. Fir NW 1/4 NW 1/4 S 5/8 E 18' Part scribe visible "T33"

16" Cedar NW 1/4 NW 1/4 NW 1/4 NW 1/4 5' Tree partly uprooted no scribe vis

No trace of 10" Maple SW 1/4 SW 1/4 or cor stone - Ren # 2

Renewal

Set Brass cap at Sec cor NW 1/4 County Surveyors office

T33S R7W

53/52  
510/511

1968

New Bearing Trees

30" D. Fir N 1/2 E 88' Scribed T33S R7W S2 CS BT

42" D. Fir East 11' Scribed T33S R7W S11 CS BT

Relocated & Rescribed  
OBT

22" cedar NW 1/4 NW 1/4 Scribed T33S R7W S3 CS BT

Note: This cor lies East of crest approx 23'

3-12-68

D.K. J.W.O. G.S. File No. 5426 114

DIETZGEN NO. 388-6