

Reverse

35 | 36
2 | 1

T 285 RBW
T 295 RBW

Found:

(1929 BT's)

12" B. Oak NW 1/4 N 66 E 128°
Rotten Face Reverse Sinking "RBW"

8" W. Oak NW 1/4 S 20 E 91°
shows spot.

No Trace of N W or SW Trees

Brass cap at sec cor MKD.

General Land Office Survey

35 | 36
2 | 1

1929

New Bearing Trees

9" W. Oak (double) S 15 W 86°
(T 295 RBW 52 CS BT)

9" D. Fir N 19 E 29°
(T 285 RBW 536 CS BT)

No Trees available in NW quad.

This cor lies 1/2 S-W
of fence cor.

11-29-66



J.M.D.
T 295
C.F.S.

DIETZGEN NO. 385-6

XO

#128 T 295 RBW
#129-1 T 298W

C. S. File No. 58/28 6