

Renewal

$\frac{36}{1}$

7283

T293

RBW

Found

orig. BT's

20" B.O. NEW BOUND S69 E 51 $\frac{5}{4}$
opened for similar "S"

30" W.O. NEW BOUND NBW 63 $\frac{1}{4}$

No Trace of 1929 'BT's'
evidently Removed when fence was
put in.

Brass cap at $\frac{1}{4}$ sec cor MKD.

General land office survey

DIETZSEN NO. 385-6

$\frac{1}{4}$ $\frac{36}{1}$

1929

New Bearing Trees

6" D. Fir S 92 E 59 $\frac{0}{4}$
scribed $\frac{1}{4}$ S 1 cs BT

18" D. Fir North 45 $\frac{7}{4}$
scribed $\frac{1}{4}$ S 36 cs BT

This cor lies North of fence
cor $\frac{1}{4}$ S



11-29-66
J.M.G.
T.M.K.
C.L.B.

#129-728-BW

♀ #130

C. S. File No. 54/38 $\frac{1}{2}$