

Renewal 514 513 7295 RBW

Found

Brass cap out of the ground 1924  
General Land Office Survey

4 5A/513

1924.

Orig B.T.

30" D. Fir Now 37" S 12W 52 1/2  
Part Scribed 1/4 S

(1924 B.T.)

16" D. Fir Now 50" N 89E 5 1/2  
spaced for scribe "1/4" "1/3"

22" D. Fir Now 17" N 34W 13 1/2  
shows good scar

Renewed:

Reset Brass cap using all Bearings  
& distances to Bearing Trees

New Bearing Tree

7" D. Fir S 55 E 38 1/2  
Scribed 1/4 513 CS BT

11-30-66

~~W.M.G.~~  
~~H.M.G.~~  
C.P.S.

Ox #132

C. S. File No.

54/28-8