

Renewal $\frac{39}{2} / 30$ 7295 7302 RBW

Found:

10" D.F.V. Now down Rather N80E 15^o
 20" D.F.V. Now 27" S 43E 30^o
 Bark Scribe visible BW 2
 30" D.F.V. Now down Rather S 53W 9^o
 12" Cedar Now down N30W 8^o

Renewal

Set Brass cap at sec. cor 1042
 county Surveyors office

T295 RBW

$\frac{529}{52} / 535$

T305

1979

DIETZGEN NO. 388-6

New Bearing Trees:

26" D.F.V. Scribed N25W T295 RBW S59 CS 20^o
 27

8" W.F.V. Scribed T295 RBW S 53 E 21^o
 Reblazed & Rescribed

27" D.F.V. Scribed T305 RBW S 2 CS 30^o
 31

Note:
 This cor lies approx 200'
 East of S75.

2-9-79

~~CS~~
~~CS~~
~~CS~~

#93 T30
 #149-T29

C.S. P. H. W. 54/80-24