

Renew Sec. Cor. R3W $\frac{513}{524}$ | R2W T275

Fd. one B.T. as follows

ORIG. 30" Now 38" FIR S. 38° E. 19' ft

This BT was obliterated in 1911

Retrace ment of Range line, only
fragmentary Bark scribe remaining
as follows - " / / / " N.E. & N.W.

B.T.'s gone - No Trace. Find a large
hole where S.W. Bt would have
been. old Blazes to N. of cor.

Set 1" I.P. & Brass cap MKd.

"COUNTY SURVEYORS OFFICE

1966 T275 R3W $\frac{513}{524}$ | R2W" Set

~~the~~ mound of stone - MARK New

B.T.S -

8" W. FIR S, 67° OW, 5 1/2 ft.

Mkd. "T275 R3W 524 CS BT"

8" W. FIR N, 70 1/2° OW, 15 1/2 ft.

Mkd. "T275 R3W 513 CS BT"

This cor. Lies on West slope
approx 440 ft. N. of C.C. - also

find 36" cedar ~~at~~ 38 ft. out of place

the blaze & fragmentary scribe & good "S" does
not look orig. Dec. 29, 1966

[Handwritten signature]

U.R.T.
J.H.
D.W.

* C.W. J.W.B.

S. File No. 54/2 -2