

Review $\frac{1}{4}$ 519 | 520 T265 R2W

Fd. C.B.T. 25 follows -

Orig. 20" Now 32" Fir N. $86\frac{1}{4}^{\circ}$ W. 33 $\frac{1}{2}$ ft.

alive we open & find "B" scribble

No Trace of Maple to S.E. set 1" I.P.

Brass cap MKd. "COUNTY SURVEYOR'S
OFFICE 1967 T265 $\frac{1}{4}$ 519 | 52 R2W"

& MK. New B.T.S. -

Q.B.T. 32" D. Fir N. $86\frac{1}{4}^{\circ}$ W. 33 $\frac{1}{2}$ ft.

Mkd. " $\frac{1}{4}$ 519 CS BT" in Bark.

40" D. Fir N. 54° E. 31 $\frac{1}{2}$ ft.

Mkd. " $\frac{1}{4}$ 520 CS BT" in Bark.

12" Hemlock N. 77° E. 69 $\frac{1}{2}$ ft.

Mkd. " $\frac{1}{4}$ 520 CS BT"

This cor. lies on very steep
northerly slope. we find no trace
of cor. stone called for.

July 17, 1967

U.P.T.

J.H.

D.W.

(Signature)

45

O.K. J.W.B. C.S. File No. 54/10-16