

Renew #3 cor. of Tract 38 T26S R2W
Fd. 1918 G.L.O. Brass cap firmly set &
MKd. " T26S S34 R2W | ^{3TR38} " & in good
condition. The B.T. for this cor
was apparently destroyed in recent
logging. The Brass cap for the
1/4 cor of sec's 34 & 35 bears north
12[±] ft 25 called for in field notes.
we MK. new B.T. -

10" cedar N. 74° E. 95[±] ft.
MKd. " 3TR38 CS BT "

This cor lies on steepest
slope - 100 ft west of temporary
log road.

July 28, 1967

V.R.T.
J.H.
D.W.

V.R. Tracy

#66

D.K. J. W. B.

C.S. File No. 54/AD-41