

Renew #4 OR SW. COR. TRACT 37 T26SR2W
Fd. O.B.T. 25 Follows -
Orig. 40" Now 48" FIR N. 19° E, 35 1/2'
2 1/2' - shows good SCAR. do not open
after much excavation in area of
large turned out FIR, we find
I.P. & BRASS CAP called for, out
of position, in good cond. we
reset in proper locus. BRASS
CAP MKD. "T26SR2W TR 37 1/4 1918"
& MK. New B.T. -

5" W FIR N. 65° E, 18 1/2' Ft.
MKD. "4TR 37 CS BT"

This COR. Lies on steep
E. slope in Heavy timber.

August 23, 1967

U.R.T.
J.H.
D.W.

(Handwritten signature: U.R.T. Tracy)

OK J.V.S.
#90

C.S. File No. 54/40-72