

Review Sec. Cor.  $\frac{522}{527} | \frac{523}{526}$  T275 R2W

Fd. orig. 24 " Now 28 " Hemlock cor Tree  
High Stumped - 7 ft. high - scribe on all  
four sides & o.B.T.s as follows -

orig. 36 " Now 40 " FIR N. 4° E. 37  $\frac{6}{4}$  ft.  
Now stump - shows scar.

orig. 24 " Now 26 " Hemlock S. 44° E. 35° ft.  
Now stump - scribe visible - no

Trace of o.B.T.s NW or SW 2 + 2'

point 1  $\frac{5}{2}$  ft East of center of cor.

Tree set 1" I.P. & BRASS cap MKd

"COUNTY SURVEYOR'S OFFICE 1968

T275  $\frac{522}{527} | \frac{523}{526}$  R2W " & MK New B.T.s -

5" D. FIR S. 32 ° W. 12  $\frac{6}{4}$  ft.

Mkd. " S 27 CS BT "

5" D. FIR S. 15 ° E. 21  $\frac{4}{4}$  ft.

Mkd. " S 26 CS BT "

5" D. FIR N. 16° E 18  $\frac{2}{2}$

Mkd. " S 23 CS BT "

6" D. FIR N. 32 ° W. 34  $\frac{3}{3}$  ft.

Mkd. " S 22 CS BT "

Note: Bearings & Dist's to New B.T.s from  
BRASS cap.

April 18, 1968

W. R. Tracy

U.R.T.  
J.H.  
U.P.

616.576 No. 52/52-77