

Renew $\frac{1}{4}$ 528 | 527 T275 R2w
Fd. $2\frac{1}{2}$ " Alum. Cap (see Note Below)
 $1\frac{1}{2}$ " I.P. alongside See Ren # 22

† B.T.s as follows -

ORIG. 24" Now 28" FIR N. $84\frac{1}{2}$ ° E, 14⁵ ft.
Now STUMP - scribe visible on
old blaze, S.W. orig. B.T. gone.

24" FIR STAMP S. 28° W, 34⁵ ft.
scribed " $\frac{1}{4}$ 528 BT" (US P14 B.T.)

Set 6 ft. steel fence post along
side Alum. Cap. & MK. New B.T.s -

6" D. FIR S. 4° W, 103³ ft.

Mkd. " $\frac{1}{4}$ 528 CS BT"

48" FIR STUMP N. 13° E, 26² ft.

Mkd. " $\frac{1}{4}$ 527 CS BT" (8 ft. high STUMP)

Note!
The Alum Cap is Mkd " $\frac{1}{4}$ 527 | 528"
should be 528 | 527.

Oct 16, 1968

V.R.T.
J.H.

V.R. Tray

D.K. J.W.B.

#77

C.S. File No. 54/20²³