

Renew Closing Cor. <sup>534 | 535 T275 R2W</sup>  
<sub>(UNRECORDED)</sub>  
T285

Fd. U.S. Plywood Alum. Cap MKd. "<sup>534 | 535</sup><sub>52</sub>"

set FROM O.B.T.S NOW ONLY sawed STUMPS

Remain. we find recent new B.T.S, also

STUMPS MKd by U.S. Plywood as follows -

16" Hemlock STump N. 45 ° W. 22 <sup>5</sup> ft,

Mkd. "534 BT" & Alum. Tag MKd. "4287"

40" cedar STump S, 62 ° E, 25 <sup>6</sup> ft,

Mkd. "52 BT" & Alum. Tag MKd. "4287"

We set 6 ft steel fence post

alongside Alum Cap & MK. new B.T. -

9" cedar N. 41 ° E, 58 <sup>1</sup> ft,

Mkd. "T275 R2W 535 cc cs BT"

This cor. lies 120 ft, East

of A.P. of <sup>534</sup>/<sub>52</sub> in clear cut

unit. (Record Dist. Bet. cor. 112 <sup>2</sup> ft.)

OCT 22, 1968

URT JP  
JH W.P.  
V.P.

q/RT Racy

G.K. J.W. B.

#93-127-2

C.S. File No. 54/40-91