

Renew $\frac{1}{4}$ 515 614 T275 R2W

Fd. 4.5. Plywood Alum. Cap & B.T.s

25 Recorded in Ren. #32 25 Follows -

Orig. 10" Now 16" Yaw N. 20° E. 38² ft.

Dead - scribe visible on open blaze.

Ren. #32 B.T. - 7" Yaw N. 48 $\frac{1}{2}$ ° W. 40² ft.

Dead - Nearly Tipped out. This cor.

Lies in clear cut area - No trees or

suitable stumps close for new B.T.s -

We set $\frac{5}{8}$ " I.R. 5° ft. South and

$\frac{5}{8}$ " I.R. 15° ft. South of cor. &

Set 6 ft. steel fence post along

side Alum. Cap.

Nov. 8, 1968

V.R.T.
F.W.J.
V.P.

V.R.T. Tracy

OK'
J.V.H.

#96

C.S. File No. 54/40-110