

Renew S.  $\frac{1}{4}$  S. 11 T27 S R2W

Fd. O.B.T.s as follows -

Orig. 22" Now 36" W. FIR S, 23° E, 17 $\frac{1}{2}$  ft.

Now sowed stump - we open & find

" $\frac{1}{4}$  S 14 BT" scribe & Reverse.

Old N.E. B.T. Down - shows scar.

we do not find cor. stoned & c.

Fire trail at cor. point set

1" I.P. & Brass cap MKd. COUNTY

SURVEYOR'S OFFICE 1968 T27 S

$\frac{1}{4}$  S. 11 R2W" & MK. New B.T.s -

10" cedar S, 44° E, 51 $\frac{1}{2}$  ft.

Mkd. " $\frac{1}{4}$  S 11 CS BT"

10" cedar S, 50° W, 53 $\frac{1}{2}$  ft.

Mkd. " $\frac{1}{4}$  S 11 CS BT"

The S.  $\frac{1}{4}$  Sec. 11 Recorded in

Re. # 44A Bears N. 19° E. 27 $\frac{1}{2}$  ft.

Nov 12, 1968

V.R.T.  
F.W.V.  
V.P.

J.H.  
W.P.

V.R.T. Tracy

Over

#130

C.S. File No.

D.K.  
J.W.D.  
54/40-113

ON subsequent visit to  
S. 1/4 Sec 11 we find U.S. Plywoods  
Alum. cap removed & logging  
Activity Beginning - we mark  
more B.T.s - as follows

40" D. Fir STUMP N. 89° E. 37 1/2 ft.  
Mkd. "Y45NCSBT"

48" D. Fir STUMP N. 75° W. 43 1/2 ft.  
Mkd. "Y45NCSBT"

U.S. Plywoods B.T. Recorded in  
Ren. # 44A-2 10" Yew N. 9° E.

54 1/2 ft. - scribe visible "Y45NCSBT"  
A Alum. Tap # 4287 - Cedar B.T.s  
Mkd. by us in Sec 14 both on at this  
time.

Dec. 23, 1968

U.P.T.  
F.W.J.  
U.P.

~~U.P.T. Ray~~

O.K.  
J.W.B.