

Renew Sec. COR. R2W  $\frac{518}{519}$  T27S R1W  
Fd.  $\frac{3}{4}$ " I.R. under 40" Log &  
40" Fir Stump N.  $34^{\circ}$  E, 60" ft.  
scribed "T27S R1W 518 CS BT"  
25 Recorded in Rev. #44 of 27-2.  
24" Hemlock snag now down &  
only decayed remains of stump  
in place. we saw 40 out of 27  
COR. point in place of I.R. set 1"  
I.P. & BRASS CAP MKD. COUNTY  
SURVEYORS OFFICE 1968 T27S  
R2W  $\frac{518}{519}$  R1W - Resct I.R. along  
side BRASS CAP - also set 6"  
ft steel fence post along  
side BRASS CAP - NO TREES OR  
STUMPS available FOR B.T.S -  
This COR. Lies approx 125 ft.  
west of Road # 274 L in logged  
off area - now densely covered  
with Greasewood BRUSH.

Nov. 13, 1968

V.R.T.  
F.W.J.  
V.P.

H.P. Tracy

C.K. J.W.B.

#21-727-1  
#100

G.S. File No. 54/40-114