

Renew  $\frac{1}{4}$  522/523 T275 R2W

Fd. U.S. Plywood  $\frac{3}{4}$  in. Cap in place  
& B.T.S. as Recorded in Ren # 26  
as follows -

60" cedar STump N.  $37^{\circ}$  W. 53<sup>0</sup> ft.

scribed " $\frac{1}{4}$  522" & Alum tag # 4287

30" cedar STump S.  $58^{\circ}$  E. 39<sup>±</sup> ft.

scribed, " $\frac{1}{4}$  523"

we MARK New B.T.S. -

10" Hemlock (Schoolmann) N.  $53^{\circ}$  W. 47<sup>±</sup> ft.

Mkd. " $\frac{1}{4}$  522 CS BT"

8" D. Fir S.  $39^{\circ}$  E. 45<sup>±</sup> ft.

Mkd. " $\frac{1}{4}$  523 CS BT"

Set 6<sup>0</sup> ft. Steel fence post

along side BRASS cap - This

COR. Lies at foot of N.W.

Slope in Marshey area

Nov, 22, 1968

V.R.T.  
F.W.T.  
V.P.

V.R. Tracy

#106

C. S. File No.

0.4.  
F.W.T.  
V.P.  
57/40-126