

Renew $\frac{1}{4}$ 523/524 T275 R2W

Fd. O.B.T.s as follows -

ORIG. 10" Now 18" Hemlock S. 85° E 21' $\frac{1}{2}$ ft.

Now stump - SCRIBE visible on opened
Blaze.

ORIG. 8" Now 10" Yew N. 80° W. 15' $\frac{1}{2}$ ft.

Down under Logging debris - SCRIBE vis.

We find NO TRACE of 2' $\frac{1}{2}$ " Alum. cap
called for in Ren. # 28 - probably

Removed During Recent Logging
at cor. point set 1" I.P. & BRASS CAP
MKd. " COUNTY SURVEYORS OFFICE

1968 T275 $\frac{1}{4}$ 523/524 R2W " & "

MK. New B.T.s -

5" Hemlock S, 21° E. 20' $\frac{1}{2}$ ft.

MKd. " $\frac{1}{4}$ 524 CS BT "

10" Yew N, 75° W. 15' $\frac{1}{2}$ ft.

MKd. " $\frac{1}{4}$ 523 CS BT "

THIS COR. LIES 135 ft. NORTH
OF CREEK 6 ft. wide course
N.E.

NOV. 26, 1968

V.R.T.
F.W.J.
V.P.

V.R.T. Tracy
#108)

C. S. File No.

54/40

O.K.
J.W.B.
-128