

Renew $\frac{1}{4}$ $\frac{50}{31}$ T275 R2W
Fd. TRUCK Axle at cor. point
MKd. " T275 R2W $\frac{1}{4}$ $\frac{530}{331}$ 1962" & BTs

25 follows - (See Ren. # 29)

Orig. 30" Now 34" Hemlock N. 46° W. 12⁵ ft.
Now Decaying STump - "BT" scribe
visible.

Ren. BTs - 20" D. FIR STump N. 52 $\frac{1}{2}$ ° E. 36³ ft.
scribed " $\frac{1}{4}$ 530 BT" & Alum. Tag # 4287

S.W. BT. STump Turned out & Lying
face Down - we set 6 ft. Steel
fence post along side Axle &
MK. New BT. -

4" D. FIR N. 57° E. 36⁰ ft.
MKd. " 530 CS BT"

No other Trees available - This
COR. lies 165 ft East of
CREEK course N. & approx.
400 ft E. of Road N. & S.

Nov. 27, 1968

V.R.T.
F.W.J.
V.P.

V.R. Tray

O.K.
S.W.B.

#109 ✓

C.S. File No. 57/40-131