

Renew Sec. Cor. $\frac{55}{58} \frac{54}{58}$ T275 R2W

Fd. O.B.T.s as follows -

ORIG. 30" NOW 38" FIR N. 80° W. 13 $\frac{3}{4}$ FT.

alive - " S 5 BT " BARK SCRIBE

Visible - poor cond.

ORIG. 20" NOW 30" FIR N. 45° E. 19 $\frac{5}{8}$ FT.

alive - Remains of AXE BARK BLAZE

NO SCRIBE OR SCAR - also hole where

S.E. B.T. would have been.

at COR point set 1" I.P. & BRASS

cap MKd. " COUNTY SURVEYORS

OFFICE 1968 T275 $\frac{55}{58} \frac{54}{58}$ R2W "

& MK. New B.T.s -

8" D. FIR N. 88° E. 13° FT.

Mkd. " T275 R2W 54 CS BT "

7" D. FIR N. 39° W. 19 $\frac{5}{8}$ FT.

Mkd. " T275 R2W 55 CS BT "

This cor. lies on steep East

Slope 69 $\frac{3}{4}$ ft. West of

closing cor. of Sec's 8 & 9.

Dec. 5, 1968

VRT
F.W.J.
V.P.

VRT Tracy

3118
0

C.S. File No. $\frac{54}{54} \frac{140}{143}$

O.K.
5.2.19