

Renew Sec. Cor. $\frac{516}{521} / \frac{515}{522}$ T275 R2W

Fd. unrecorded $\frac{3}{4}$ " IRON Rod 2+

Cor. point & O.B.T.S 25 follows -

Orig. 24" Now 40" cedar N. 68° E. $3 \frac{5}{8}$ ft.

Record 132 2 ft. - 2 live previously opened

shows scribe MKs - 55+ years Ring count.

Orig. 18" Now 24" cedar S 15° E. $4 \frac{6}{8}$ ft.

Record - S. 25° E. - 2 live - we open & find

scribe & Reverse under 55+ years Ring count.

Orig. 12" Now 21" Fir S. 19° W. $4 \frac{6}{8}$ ft.

2 live - shows good scar - we do not open.

Orig. 30" Now 36" Fir N. $47 \frac{1}{2}^{\circ}$ W. $6 \frac{7}{8}$ ft.

Record Bearing N. 52° 40' W.

2 live - scribe visible on unhealed &

decaying blaze - in place of I.R. at cor.

set 1" I.P. & BRASS cap MKd. COUNTY

SURVEYOR'S OFFICE 1968 T275

$\frac{516}{521} / \frac{515}{522}$ R2W " & Reset I.R. along side

MK. New B.T.S -

11" W. Fir N. 69° W. $30 \frac{2}{8}$ ft

Mkd. " T275 R2W 516 CS BT

11" W. Fir S. 52° W. $25 \frac{2}{8}$ ft.

Mkd. " T275 R2W 521 CS BT "

12" W. Fir S. 81° E. $29 \frac{1}{8}$ ft.

Mkd. " T275 R2W 522 CS BT "

" cedar N. 21° E. $23 \frac{2}{8}$ ft.

Mkd. " T275 R2W 515 CS BT "

April 18, 1968

#74 R. Tracy

OK. T. W. B. V. R. T. J. H. File No.

57/10-146