

30/29

Review Sec. Co. R. 31/32 T275 R2W

Fd. 2 1/2" Alum Cap set by W.S. Plywood  
see Rev. #24 & Remains of one B.T.  
17" Hemlock N. 51° W. 58 1/2 ft.

Badly Buried Stump - Blaze destroyed.  
All other B.T.'s Destroyed by Logging.

Set 6 ft. Steel fence post along  
side Alum. cap. & MK. New B.T.s -

26" D. Fir N. 8° W. 161° ft.

Mkd. "T275 R2W 530 CS BT"

16" W. Fir N. 89° E. 117 1/2 ft.

Mkd. "T275 R2W 529 CS BT"

NO TREES available to South. This  
Co. R. lies in logged off unit on  
moderate N.E. slope.

Dec. 11, 1968

V.R.T.  
F.W.J.  
V.P.

A. R. Tracy

O.K.  
J.V. I.O.

♀ #120

C. S. File No. 54/40-151