

528/527  
533/534

T27S R2W

Review Sec. Cor.  
Fd. 1 1/2" I.P. with 1" steel Pipe & Alum  
cap MKd "527/528"?  
U.S. Plywood & Stumps of OBTS & New  
BT. - we set 6 ft. steel fence post  
& MK. new BTs -

4" D. FIR N. 25 1/2° E. 64 ± ft.

Mkd. "527 CS BT"

4" D. FIR N. 73° W. 4 ± ft.

Mkd. "528 CS BT"

5" D. FIR S. 69° E. 32 ± ft.

Mkd. "534 CS BT"

All old stumps in place & scribe  
visible - this cor. lies in flat  
Logged off area - from in Reprod  
of D. Fir, Hemlock & cedar.

Dec. 13, 1968

URT  
F.W.J.  
UR

~~TAM WILU  
CHANGE~~

V.R. Tracy

Note - Alum cap mismarked for  
sec's 27 & 28

O.H.  
J.W.B.

#128

C.S. File No. 54/40-156