

529/528
Renew Sec. Cor. 532/533 T27S R3W

Fd. $\frac{3}{4}$ " I.R. Not set & B.T.s follows -
See Ren. # 53

Orig 50" Now 60" Pine S. 55° W, 59 $\frac{1}{2}$ ft.
Now sawed stump - scribe visible.

Ren. B.T.s -

44" D. FIR N. 40° W, 40 $\frac{1}{2}$ ft,

2 live & OK. - good scribe -

28" Madrone S 8° E, 56 $\frac{1}{2}$ ft.

2 live - OK. - good scribe -

NE. B.T. gone - 2^d cor. point

set 1" I.R. & BRASS cap MKd "COUNTY

SURVEYOR'S OFFICE 1969

T27S $\frac{529}{532}$ / $\frac{528}{533}$ R3W " Reset I.R.

Along side BRASS cap & MK.

New B.T. -

16" D. FIR N. 71° E. 60 $\frac{1}{2}$ ft

Mkd. "T27S R3W 528 CS BT"

No suitable trees available in

Sec 32. This cor. lies on

Very steep Northerly slope.

June 20, 1969

O.K.
J.W.B.

V.R. Tracy

V.R.T.
J.G.H.
U.D.P.

#114 L

C. S. File No. 54/40-175