

Renew Sec. COR. ^{514 | 513} 523 | 524 T275 R3W

Fd. 4" x 14" x 22" COR Stone MKd
with 5 notches on West edge & 3
notches on South edge, in place & B.T.s
as follows - (see Ren # 7)

20" Now 24" FIR N. 45° E. 4 2/3 ft.

alive - shows good SCAR

8" Now 13" FIR N. 22° W. 2 8/9 ft.

alive - shows good SCAR - ORIG SE.

B.T. - now sawed stump & other

Ren # 7 B.T. To S.W. now sawed stump.

at COR point in place of COR Stone

set 1" I.P. & BRASS cap MKd.

"COUNTY SURVEYORS OFFICE

1969 T275 ^{514 | 513} 523 | 524 R3W " & Reset

stone along side. MK. new B.T.s -

11" D. FIR S. 81° W. 26 8/9 ft.

Mkd. "T275 R3W S 23 CS BT"

10" D. FIR S. 49° E. 38 5/8 ft.

Mkd. "T275 R3W 524 CS BT"

This COR. lies on moderate
S.W. slope.

Sept. 9, 1969

#1102 R T Tracy

U.R.T.

J.G.H.

U.D.P.

O.W.
J.W.H.
178

C.S. File No.

54/40-178