

S4/S3  
59/510

T32S R9W

Found:

20' D. Fir Now 23" N41E 23'  
Shows good Scar

20' D. Fir Now 26" S72W 36E  
Shows good Scar

18' D. Fir Now 22" N26W 29E  
Shows good Scar

19" Yew Now 20" S66W 39E  
(Record S64W 38E)

Faint scribble visible "g." "s."  
Face Badly Bolted

17/30 Brass cap at sec cor M&P  
General Land office

T32S R9W

S4/S3  
59/510

1917

Relocated & Rescribed

20" Yew S66W 39E  
Scribed T32S R9W S10 ea at

Note:

This cor has approx 200E East  
of logging rd.

Also: Brass cap is flush with ground  
All trees tagged & location tag  
on rd.

Wrote  
Robert  
Ran #1-2

5-19-67  
JWB  
JEB

#22 O.N.J.W.B.

C.S. File No. 51/44<sup>S</sup>

DIETZEN NO. 385-6