

Renewal

$\frac{55}{58} | \frac{51}{59}$

7325 R9W

Found:

16" D. Fir NOW 18" N47E 10¹/₂
spaced for scribe "W"

22" D. Fir NOW 23" N79W 27¹/₂
shows good scar

40" D. Fir NOW 41" S10W 27¹/₂
shows good scar

S.E. Chingupia down Rotten

R/soil Brass nap at Sec car MKR

General land office

7325

$\frac{55}{58} | \frac{51}{59}$
R9W
1917

DIETZGEN NO. 385-6

New Bearing Tree

21" D. Fir S40E 26¹/₂
Scribed 7325 R9W S9 CS BT

5-22-67

725

O.W. J.W.B.

C.S. File No. 54/44-8