

Renewal

515 514
522 523

T323 R9W

Fowards

40" D. Fir N41W 76" N51E 67Z
shows good scar

36" D. Fir N41W 41" S53W 29Z
shows good scar

29" D. Fir N41W 28" N43W 24Z
shows good scar

36" D. Fir N41W 41" S47E 32Z
shows good scar

Also Brass cap at sec cor N430,
General land office

T325 R9W

515 514
522 523

1917

New Bearing Tree:

6" D. Fir S26E 27Z
saw-bad T325 R9W S23 CS RT

Note: This car lies approx 180°
south of Logging Rd.

5-31-67

~~J. W. B.~~
~~522~~
~~523~~
J. W. B.

#29

* O. K. J. W. B.

C. S. File No. 54/44-14

DIETZGEN NO. 385-6