

Renewal

523/524
526/525

T325 R9W

Found:

36" P. Fir Now 5099 N5W 19³
Scribe Visible T325 R9W S23 BT

40" D. Fir Now 5099 S52W 27³
Scribe Visible S26

36" P. Fir Now Down N32E 39^E
Shows Scar

30" D. Fir Now 37" S25E 59^E
Shows good Scar

Also Brass Cap at See cov Mark

General Land Office

T325 R9W

523/524
526/525

1917

New Bearing Trees

36" D. Fir Now N6E 32^E
Scribed T325 R9W S24 CS BT

41" D. Fir Now S52W 39^E
Scribed T325 R9W S26 CS BT

6" Ch. Fir Now N24W 22^E
Scribed T325 R9W S23 CS BT

Note: cov lies 330^E East of R
Ridge Top & 600^E South of
Ridge Top

6-1-67

[Signature]
JCS

32
O.K. J.W.B.

C.S. File No. 57/14-16

DIETZEN NO. 385-6