

RENEWAL

57/58

T325 R9W

518/517

FOUND BK.

18 CHINAQUIN NOW 12' SNA5 N57W 46 1/2 FT

SHOWS SCRIBING OF (T325 R9W 57 BT)

40" D PINE NOW 42' SNA5 N46E 25 1/2 FT

SHOWS SCRIBING OF (T325 R9W 58 BT)

40" D FIR NOW 42' SNA2E 48 1/2 FT

SHOWS GOOD FACE

18 CHINAQUIN NOW DOWN S87W 25 1/2 FT

SHOWS FACE

ALSO FOUND BRASS CAP AT COR. MKD

U.S. GENERAL LAND OFFICE SURVEY

T325

57	58
518	517
R9W	
1417	

NEW BTS

14" D FIR N80 1/2 W 67 1/2 FT

SCRIBED T325 R9W 57 CS BT

6" D FIR N34E 28 1/2 FT

SCRIBED T326 R9W 58 CS BT

14" CHINAQUIN S74W 43 1/2 FT

SCRIBED T325 R9W 518 CS BK 6-7-67

ELM  
ERLW

\*#33

ON. J.W.B.

C. S. File No.

57/44-20

DIETZEN NO. 385-6