

Renewal

56/55
57/58

T325 R9W

Found:

9" Pine New 10" 539W 10E
Burst from scribe visible
"5325" "10" other marks not legible
No other Bearing Trees found:

Also

Brass cap at See car MAP.

General Land Office

T325 R9W

56/55
57/58

1917

Renewals:

New Bearing Trees:

8' D. Fir	Scribed	T325 R9W	S63W	57	CS	BT	15'
15' Pine	Scribed	T325 R9W	N20W	56	CS	BT	20'
15' D. Fir	Scribed	T325 R9W	S70E	58	CS	BT	19'
5' Chingupin	Scribed	55	N69E	CS	BT		19'

Note:

This car lies 20' South of
small Ravine

6-7-67

[Handwritten signature]
JCS

#34

D.K. J.W.B.

C.S. File No. 54/44-2

DIETZGEN NO. 385-6