

RENEWAL

$\frac{1}{4}$  S10  
S15

T32SR9W

Found: B.C

8" D. FIR NOW 28" N65E 332 FT

Shows A FACE

B'S. PINE NOW DOWN S81W 372

DOWN ROTTED

ALSO FOUND BRASS CAP AT  $\frac{1}{4}$  COR. MKD.

U.S. GENERAL LAND OFFICE SURVEY

$\frac{1}{4}$  S10  
S15

1917

RECORDED

28" D FIR N65E 332 FT

SCRIBED Y4S10CS BT

NEW BT

12" D FIR S16W 102 FT

SCRIBED Y4S15CS BT

6-8-67

FUT

ON

CRW

\*#36

O. N. J. W. B.

C. S. File No. 54/44-24

DIETZEN NO. 385-6