

Renewal

$\frac{512}{513}$

T325 B9W

Found:

12" D. Fir Now 19" N33W 126°
shows good scar

No Trace of SW BT (5" Fir)

Also Brass cap at Sec. cor MKP,

General land office

T325

$\frac{512}{513}$

B9W

1917

Renewal

New Bearing Trees

9" D. Fir Scribed T325 B9W 562W 213 CS BT 15°

No other good trees closer (NW quad)
Note:

This scar lies on top of
ridge, approx 260' North of
Jeep Rd.

6-16-67

[Handwritten signature]

O 742-7329

X 38

O.K. J.W.B.

C.S. File No. 54/44-41

DIETZGEN NO. 3855-B