

RENEWAL

1/4 | 60N1/2 T32S R8W

FOUND

24" D FIR NOW 30" WINDFALL S 62 W 40 2 FT

NOTE THE BT WAS ABOUT 50' DOWN THE HILL. THERE WAS A GOOD STUMP HOLE.


TO GET THE BEARING & DISTANCE FROM.

SHOW GOOD SCRIBE OF (V 4)

NOTE OTHER BT, WAS GONE.

ALSO FOUND BRASS CAP AT THE 1/4 CORNER.

US GENERAL LAND OFFICE SURVEY



RENEWAL

NEW BTS

12" HEMLOCK N 75 E 50' ± FT

SCRIBED V 4 S 6 C S BT

10" HEMLOCK N 86 E 30' ± FT

SCRIBED V 4 S 6 C S BT

NOTE THIS CORNER LIES 50' ±

EAST OF CREEK

6-29-67

*[Handwritten signature]*  
~~11/11/67~~  
 JCB

\*66-7527

\*D2

O. W. J. W. B.

C. S. File No. 54/22-65

DIETZGEN NO. 385-6