

Renew $\frac{1}{4}$ $\frac{56}{57}$ T225 R12W

Fd. 2" I.P. & B.T. Recorded. in Rev. # 1
set by Boyer in 193625 follows -

40" spruce stump S. 29° E. 9 2 ft. (face)

Badly decayed - scribe MKs. visible.

We MK. New B.T.s -

6" spruce S. 80° E. 11° ft.

Mkd. $\frac{1}{4}$ 57 CS BT"

14" Alder N. 1° W. 12³ ft.

Mkd. $\frac{1}{4}$ 56 CS BT"

We find no trace Boyers S.W. BT. -

This cor. lies 8° ft. N. 81° W.

of old fence cor., fences S & E.

on Easterly slope Ridge.

June 2, 1967

J.W.B.
V.R.T.
J.H.
D.W.

~~Q.R. Trace~~

D.W. J.W.B.

* 0#45
U.S. File No.

54/46-6