

Renew Sec. Cor. <sup>56</sup>57 | <sup>55</sup>58 T225 R12W

Fd. one O.B.T. as follows -

ORIG. 40" Now 48" SPRUCE S. 86° W. 35° FT.

Now Badly decayed STUMP - we open &  
Find "57 T225 R12W" scribed & Reverse.

We find NO Trace other ORIG. B.T.s -

Set 1 "I.P. & BRASS CAP MKd." COUNTY

SURVEYOR'S OFFICE 1967 T225

<sup>56</sup>57 | <sup>55</sup>58 R12W " & MKd. New B.T.s -

20" SPRUCE N. 46° E. 32<sup>7</sup> FT.

Mkd. "T225 R12W 55 CS BT"

20" SPRUCE S. 82° E. 35<sup>5</sup> FT.

Mkd. "T225 R12W 58 CS BT"

11" SPRUCE S. 40° W. 31<sup>8</sup> FT.

Mkd. "T225 R12W 57 CS BT"

12" Alder N. 66° W. 28<sup>7</sup> FT.

Mkd. "T225 R12W 56 CS BT"

This COR. LIES IN CANYON BOTTOM  
COURSE S. 25° E. ONE E. side of Ridge  
approx 360 FT. FROM TOP.

June 2, 1967

J.W.B.  
V.R.T.  
J.H.  
D.W.

~~W.R. Tracy~~  
\* #44

O.K. J.W.B.

U.S. File No.

54/42-B