

RENEWAL

1/4 53 | 52 T335 R6W

FOUND UNRECORD 1/2 IRod AT 1/2 COR AND  
FOUND TO BE AT CORRECT BEARING & DISTANCE

5" D FIR NOW 9" S 64 E 34 E FT

SHOWS SCRIBING OF (1/4 52 BT)

16" D FIR NOW 30" N 46 W 18 E FT

SHOWS SCRIBING OF (5)

NEW BT

26" D FIR S 10 E 14.7 FT

SCRIBED 1/4 52 45 BT

NOTE THIS LIES IN THE S.W. CORNER  
OF OLD CUTTING UNIT

10-26-67

Fwd  
JMB  
JCS

O.K. J.W.B.

File No.

54/53-34

DIETZEN NO. 385-6