

Renew Sec. Cor. $\frac{516}{521} | \frac{515}{522}$ T245 R9W

Fd. o.B.T.s 25 follows -

orig. 40" now 50" FIR S. 11° W. 7 $\frac{3}{4}$ ft.

2 live - shows good scar - we do not open -

orig. 30" now 34" FIR N. 43 $\frac{1}{2}$ ° W. 33° ft.

now snag. - we open & find scribed rock ^{5"}

orig. NE & SE B.T.s now stumps down & out of place. set 1" I.P. & BRASS COP

at cor. point MKd, "COUNTY SURVEYOR'S

OFFICE 1968 T245 $\frac{516}{521} | \frac{515}{522}$ R9W"

& MK. New B.T.s -

18" Hemlock N. 42° E. 18 $\frac{3}{4}$ ft.

Mkd, "T245 R9W S15 CS BT"

18" Hemlock S. 67° E. 27 $\frac{1}{4}$ ft.

Mkd, "T245 R9W S22 CS BT"

15" Hemlock S. 43° W. 28 $\frac{8}{16}$ ft.

Mkd, "T245 R9W S21 CS BT"

10" Hemlock N. 25° W. 26 $\frac{1}{4}$ ft.

Mkd, "T245 R9W S16 CS BT"

This cor. lies 60 ft. South of Road #

Feb. 26, 1968

VRT
J.H.
U.P.

(Signature)

005

O.K. J.W.B.

CS No. 42/65-16