

518

Renew $\frac{1}{4}$ 522 T295 R2W

Fd. 1917 G.L.O. BRASS CAP IN good condition & properly MKd. & following old B.T. -

18" Now 20" FIR S. $11\frac{1}{2}^{\circ}$ W. 30 $\frac{1}{4}$ ft.

Now STUMP - we open & find partial "BT" scribe & reverse.

3 STUMP ONLY FOR N.E. B.T. -

We MK. New B.T. STUMPS -

40" D. FIR STUMP S. 58° W. 22 $\frac{1}{2}$ ft. MKd. " $\frac{1}{4}$ 522 CS BT"

8" New STUMP N. 13° E. 26 $\frac{1}{2}$ ft. MKd. " $\frac{1}{4}$ 515 CS BT"

This COR. Lies in approx. middle of Logged off unit. on SW. Slope.

June 28, 1967

U.R.T.
J.H.

W.R. Tracy

130
*

O.K. J.W.B.

C.S. File No. 54/158¹