

Renewal

$\frac{9}{16}$

7293 R2W

Found:

12" Metal lat New stump S40W 33°
Scribe visible $\frac{1}{4}$ S 16 BT

No trace of NW 1/4 BT - Falls in
Pd ~~Plot~~

Brass cap out of ground (Mtd.)
General land office

$\frac{9}{16}$
1917

Renewal:

Reset Brass cap at $\frac{1}{4}$ corner
which falls out edge of Rd.

New Bearing Traces

18" Metal lat 524W 78°E
Scribed $\frac{1}{4}$ S 16 CS BT

24" D. Fir N84W 67°E
Scribed $\frac{1}{4}$ S 9 CS BT

FILED

RECEIVED

10-15-67

OCT. 13 1967

J. W. B.
J. W. B.
J. W. B.

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

#23

O. W. J. W. B.

C. S. File No. 54/58-4

DIETZGEN NO. 385-6