

Renewal

36/31
1/6

T29 S
T30 S R2-1 W

Found:

Brass cap at Township com MKD.
General land office
T29 S

R 536/531 R
S 51/56 L
W T30 S

OBT'S

1917

30" Pipe NAW DAWD & BURST SBNW 247

18" oak NAW Rotted out N70W 37°

18" oak NAW stub N8E 125

12" oak NAW 12" S89E 118°
opened for Scriba BT

Tree very rotten fell this
tree as it would be a hazard.

Renewal

New Bearing Trees

16" D. Fir N 49 W 26°

Scribed T29 S R2W S36 CS BT

16" D. Fir N 73 E 175

Scribed T29 S R/W S31 CS BT

Relocated & Rescribed (1907) BT'S

16" D. Fir S 9 E R(5/2E) 13°

Scribed T30 S R/W S6 CS BT

10" D. Fir S 41 W (S39 W) 33°

Scribed T30 S R2W S1 CS BT

1-15-68

2006-T29-1
20 T29-2
50 T29-1W

~~T29 S~~
~~R2 W~~
~~S36~~

D.W. J.V.M.B.

#95-T30-2W

C. S. File No. 54/59-30

DIETZGEN NO. 385-6