

Renewed S 26 / only T303 R1W

Found

42" D. Fir now 42" S78W 16 S
Shows good bear

40' Cedar now 17" N11W 20 S
Scribble visible 1/4 S 26 BT Tree being
Squashed Not in good shape

Cross cap at 1/4 cor MFD.

General land office

T303 R1W

1/4 26

1923

New Bearing Tree

15" Fir N10W 37 E
Scribbled 1/4 S 26 CS BT

Note This cor lies 61' North of
1/25 T303 R1W, Rm. 251

1-26-68

J. W. B.
J. W. B.
J. W. B.

O. K. J. W. B.