

Benewah

32 | 33  
5 | 7

130  
T31 S RW

Faded

10" D. Fir Now 28" S88W 9<sup>±</sup>  
shows good Scar

20" D. Fir Now 31" N40E 9<sup>±</sup>  
shows good Scar

12" Laurel Now 18" S74E 10<sup>±</sup>  
shows Scar

18" Pine now Stump N84W 30<sup>±</sup>

Also:

Cross cor at Sec cor NW/2

General Land Office

T30S RW

532 | 333  
55 | 34

T31S  
1923

Benewah

New Bearing Tree

12" D. Fir N 59 W 36<sup>±</sup>  
Scribed T30S RW S32.4 + 0T

Note:

This cor lies approx 65° south  
of Spring Branch.

2-5-68

~~W. J. B.~~  
~~W. J. B.~~

W. J. B.

556  
44-T21-1W

C. S. File No. 54/59-61

DIETZGEN NO. 3885-6