

Renewal

8/19
17/16

T305 R1W

Found

Broken Stone at sec cor,
with 4 grooves

24" Pipe Now snag S 82 W 9°
Burnt Face Fast 4 visible

24" Pipe Now 31 N 54 W 102°
Shows good Scar

Remains of oak about S 60 E 71°

Renewal

Set Brass cap at sec cor MKD.

County Surveyors office

T305 R1W

50/59
517/516

1968

New Bearing Trees

12" D. Fir N 70 1/2 W 29°
Scribed T305 R1W 58 CS BT

9" D. Fir N 35 E 19°
Scribed T305 R1W 59 CS BT

8" D. Fir S 38 E 131°
Scribed T305 R1W 516 CS BT

15" D. Fir S 14 W 89°
Scribed T305 R1W 517 CS BT

6-11-68

~~Handwritten signature~~

#75

O.K. J. W. B.

C.S. File No.

54/59-82

DIETZGEN NO. 385-6