

Revised only 1/18 T3081E

Found

BRASS cap at 1/4 cor NWKD,
U.S. General Land Office

1/518
1923

60" D. Fix Now 60" N58E (Rec N42E) 91°
Shows good seam

30" D. Fix Now 58" S3E 81°
Shows good seam

NEW BTS.

15" D. Fix Scribed 1/4 S18 CS BT S 73E 21°

10" D. Fix Scribed 1/4 S18 CS BT N42E 27°

Did not tie between
cores, getting to late 6-12-68

[Handwritten signature]

#12 T30142
#10 T301E
D.K. J.W.R.

G.S. File No. 54/59-67

DIETZGEN NO. 385-6