

Renewal

5/9

T305 R1W1

Found

18" D. Fir Down Bottom N 88 W 7 1/2  
opened Tree found reverse scribing of 18"

30" D. Fir Nowl snag S 18 E 15 1/2  
could not find any scribing

No Trace of Stone -

Renewal

Set Brass cap at Geyer M.D.  
County Surveyors office

T305 R1W1

1/4 S 5 1/2 E

1968

New Bearing Trees

9" Hemlock N 9 W 19 1/2  
Scribed 1/4 S 5 1/2 CS BT

16" D. Fir N 33 E 37 1/2  
Scribed 1/4 S 1/2 CS BT

6-18-68

~~J.M.G.~~  
~~J.M.G.~~  
~~J.M.G.~~