

Renewal / 519 T30S R1 E

Found

Brass cap MKD.

General Land Office Survey

T305

/ 519 1/2

1923

50' D. Fir NW 60' N2E 235'

Shows good scar

Found Probable SE BT (To many  
logs to check)

Renewal

New Bearing Trees

8' D. Fir S 16 E 123  
Scribed 1/4 519 23 BT

12' D. Fir N 17 E 73  
Scribed 1/4 519 23 BT

Note

This cor like 236'  
North of sec cor

8-28-68

24 | 19 T30S R1 W-E.  
25 |

~~236'~~  
~~237'~~  
~~238'~~

D.V. J.W.B.

#91-T20-1W

#12-1E

C.S. File No. 54/59-112

DIETZGEN NO. 388-6