

Review Sec. Cor. $\frac{55}{58} / \frac{54}{59}$ T235 R9W

Fd. O.B.T. 25 follows -

Orig. 40" Now 50" Fir N. 35° E. 21 1/2 ft.

alive - shows "T2 5" BARK scribe in

poor cond. other O.B.T.s Turned out.

set 1" I.P. & BRASS cap MKd.

"COUNTY SURVEYOR'S OFFICE

1967 T235 $\frac{55}{58} / \frac{54}{59}$ R9W" & MK.

New B.T.s -

18" Hemlock N. 79° E. 10° ft.

Mkd. "T235 R9W 54 CS BT"

18" Alder N. 35° W. 15 3/4 ft.

Mkd. "T235 R9W 55 CS BT"

15" Alder S. 53° E. 23 3/4 ft.

Mkd. "T235 R9W 59 CS BT"

No suitable Tree to S.W. This

Co.R. Lies 75 ft. East of

Chick course N.

Dec 18, 1967

V.R.T.

J.M.

V.P.

(Handwritten signature)

J.W.B.

#48 ✓

O.K.

S. File No.

54/60-16